

# **ATTACHMENT A**

## **Summary of submissions by category**

Category	Submitters
<b>Infrastructure Capacity</b>	
The water supply system does not have sufficient capacity to accommodate PC34.	<b>S01</b> C and M Allen [D1.1], <b>S04</b> N and M Wellby [D4.2 to D4.3], <b>S05</b> S Collie {D5.7}
The wastewater system does not have sufficient capacity to accommodate PC34.	<b>S01</b> C and M Allen [D1.2], <b>S04</b> N and M Wellby [D4.4], <b>S05</b> S Collie {D5.4 to D5.6}
The costs of providing for infrastructure upgrades may create a financial risk and pressure to the ratepayers of Southbridge	<b>S01</b> C and M Allen [D1.3] <b>S04</b> N and M Wellby [D4.5]
The need to ensure the adequate supply of water for fire fighting	<b>S01</b> C and M Allen [D1.4], <b>S02</b> NZFC [D2.1 to D2.3], <b>S04</b> N and M Wellby [D4.6], <b>S05</b> S Collie {D5.8}
<b>Reverse Sensitivity</b>	
The impacts of reverse sensitivity to McMillan Drilling Ltd site	<b>S03</b> SAC [D3.8 to D3.10], <b>S04</b> N and M Wellby [D4.7 to D4.8 }, <b>S06</b> McMillan Drilling Ltd [D6.1 to D6.3}
<b>Effects on Character</b>	
The character and village amenity of Southbridge	<b>S05</b> S Collie {D5.2 to D5.3}
Loss of rural outlook	<b>S07</b> J and L Summers [D7.1 to D7.3]
Use of relocatable houses	<b>S03</b> SAC [D3.11]
<b>Growth</b>	
Little demand for growth	<b>S05</b> S Collie {D5.9}
Positives of growth	<b>S03</b> SAC [D3.2 to D3.7]