

Anna MacKenzie

From: Anderson, Clive <ckanderson@golder.co.nz>
Sent: Thursday, July 14, 2016 12:02 PM
To: Anna MacKenzie
Cc: judith.pascoe@ccc.govt.nz
Subject: RE: PC48 - updated Geotech information

Anna

I have reviewed the geotechnical letter dated 1 Oct 2012, prepared for Mr John Hayson of Silverstream Estates Ltd and can confirm that I would not expect the ground conditions related to liquefaction potential to have changed at this site since the letter was written. Further I believe the land you are considering falls within the area of low geotechnical risk as shown on this map (see link) placed on SDC's website.

https://www.selwyn.govt.nz/_data/assets/pdf_file/0004/113746/LowGeotechnicalRiskArea_Sept2013.pdf

Clive Anderson

Clive Anderson (BE Civil (Hons), MSc (Soil Mechanics & Engineering Seismology) (Distn), DIC, Dip Technology Management) | Associate - Principal Geotechnical Engineer | **Golder Associates (NZ) Limited**
Level 1, 214 Durham Street, Christchurch 8011, New Zealand (PO Box 2281, Christchurch 8140)
T: +64 3 377 5696 | **D:** +64 3 903 2405 | **F:** +64 3 377 9944 | **C:** +64 21 270 2599 | **E:** ckanderson@golder.co.nz | www.golder.com



Best Provider to Construction and Infrastructure (Australasia)

Work Safe, Home Safe

This email transmission is confidential and may contain proprietary information for the exclusive use of the intended recipient. Any use, distribution or copying of this transmission, other than by the intended recipient, is strictly prohibited. If you are not the intended recipient, please notify the sender and delete all copies. Electronic media is susceptible to unauthorized modification, deterioration, and incompatibility. Accordingly, the electronic media version of any work product may not be relied upon. Any advice provided in or attached to this email is subject to limitations.

Golder, Golder Associates and the GA globe design are trademarks of Golder Associates Corporation.

Please consider the environment before printing this email.

From: Anna MacKenzie [mailto:anna@avanzar.co.nz]
Sent: Monday, 11 July 2016 1:34 p.m.
To: Anderson, Clive <ckanderson@golder.co.nz>
Cc: judith.pascoe@ccc.govt.nz
Subject: FW: PC48 - updated Geotech information

Hello Clive

A few months ago you did a review of a previous geotechnical report you had prepared for Silverstream estates in Darfield to confirm if it was still relevant for Judith Pascoe's proposed plan change at 193 Creyke Road. Council have requested further information seeking if the attached 2012 updated report is also still relevant.

Are you able to check this and update your letter to Judith advising of the relevance of the previous geotechnical reports for this site?

Please feel free to give me a call if you have any questions.

Kind regards

Anna Mackenzie
Senior Planner BSc, MAppIsc, NZPI

Office Phone 0277422122

Head Office Address 356 Memorial Ave, Burnside, Christchurch.

Postal Address 165 Lindens Road, RD3, Koromiko, Blenheim 7273.

Email anna@avanzar.co.nz www.avanzar.co.nz

Offices in Christchurch, Timaru and Blenheim.



From: Michael Rachlin [<mailto:Michael.Rachlin@selwyn.govt.nz>]

Sent: Monday, July 11, 2016 1:14 PM

To: 'Anna MacKenzie' <anna@avanzar.co.nz>

Subject: PC48 - updated Geotech information

Hello Anna

Attached is the additional information that was supplied in 2012. This together with the original 2010 study formed the basis of the peer review by SDC's expert and their acceptance of the overall geotechnical investigations at the Silverstream site.

Kind regards

Michael Rachlin BA(Hons), BPI, MSc, MRTPI | Strategy & Policy Planner | Selwyn District Council
DDI: 03 347 2936

Selwyn District Council, 2 Norman Kirk Drive, Rolleston 7614; PO Box 90, Rolleston 7643, Christchurch
Phone: (03) 347-2800 or (03) 318-8338, Fax: (03) 347-2799
www.selwyn.govt.nz | m.selwyn.govt.nz | www.selwynlibraries.co.nz | www.selwyn.getsready.net