



Note: Not to scale and locations are approximate only

Connell Wagner

Connell Wagner Limited
195 Hereford Street
PO Box 1061
Christchurch - New Zealand

Telephone: +64 3 366 0821
Facsimile: +64 3 379 6955
Email: cwchc@connwag.com

Client

Maurice Coffey

Project

M Coffey-Cairnbrae Dr, Prebbleton

By

FI

Date

4 October 2007

Job Number


P29731-003G

Figure 1
Site location

Paper Size

A4

Revision



Note: Not to scale and locations are approximate only

Connell Wagner Limited 195 Hereford Street PO Box 1061 Christchurch - New Zealand Telephone: +64 3 366 0821 Facsimile: +64 3 379 6955 Email: cwchc@connwag.com				Client Maurice Coffey		Figure 2 Site location detail		Paper Size A4
Project M Coffey-Cairnbrae Dr, Prebbleton		Revision						
By FI		Date 4 October 2007	Job Number P29731-003G					



Note: Not to scale and locations are approximate only

Connell Wagner

Connell Wagner Limited
195 Hereford Street
PO Box 1061
Christchurch - New Zealand

Telephone: +64 3 366 0821
Facsimile: +64 3 379 6955
Email: cwchc@connwag.com

Client

Maurice Coffey

Project

M Coffey-Cairnbrae Dr, Prebbleton

By

FI

Figure 3

Geotechnical Testing Location

Paper Size

A4

Revision

Date 4 October 2007

Job Number

P29731-003G

Job Name: M Coffey-Cairnbrae Dr, Prebbleton

Job No: P29731-003

FILE LOCATION: P:\29731\003-civil\docs\Photo Prebbleton Geotech 2007-10-04.ppt



PHOTO: 1
NARRATIVE: Test pit 1



PHOTO: 2
NARRATIVE: Test pit 4. Note: Top layer sandy silt, bottom layer sandy gravel

Job Name: M Coffey-Cairnbrae Dr, Prebbleton

Job No: P29731-003

FILE LOCATION: P:\29731\003-civil\docs\Photo Prebbleton Geotech 2007-10-04.ppt



PHOTO: 3

NARRATIVE: Bottom of test pit 3. Note: No gravel at maximum depth of 5.2m




PHOTO: 4

NARRATIVE: Typical subsoil layer at depth consisting of coarse gravel and cobbles (TP6)