



SELWYN RESIDENTIAL DEFERRED ZONING | DARFIELD

GRAPHIC ATTACHMENT TO LANDSCAPE AND VISUAL ASSESSMENT

DOCUMENT INFORMATION

project

OUTLINE DEVELOPMENT PLAN

project no.

19063

address

SELWYN DISTRICT

client

SELWYN DISTRICT COUNCIL

status

FOR INTERNAL REVIEW

FOR CLIENT ISSUE

revision

A	INTERNAL REVIEW	07 AUG 2019
B	INTERNAL REVIEW	24 OCT 2019

reviewed by

AUTHOR:	AM
CHECKED BY:	NS
PEER REVIEWED:	--

document

GRAPHIC ATTACHMENT TO ACCOMPANY LANDSCAPE AND VISUAL ASSESSMENT (A4 WRITTEN REPORT)

prepared by

ROUGH & MILNE LANDSCAPE ARCHITECTS LTD.

disclaimer

These plans and drawings have been produced as a result of information provided by the client and/or sourced by or provided to Rough and Milne Landscape Architects Limited (**r+m**) by a third party for the purposes of providing the services. No responsibility is taken by **r+m** for any liability or action arising from any incomplete or inaccurate information provided to **r+m** (whether from the client or a third party). These plans drawings are provided to the client for the benefit and use by the client and for the purpose for which it is intended.

© Rough and Milne Landscape Architects Limited 2018

CONTENTS

maps, plans & visuals


SHEET	
03	Context Map
04	Selwyn District Council Planning Map

photographs

SHEET	
05	Photographs 1 & 2
06	Photographs 3 & 4
07	Photograph 5
08	Photographs 6 & 7
09	Photographs 8 & 9
10	Photographs 10 & 11
11	Photograph 12
12	Photograph 13
13	Photographs 14, 15 & 16
14	Photographs 17, 18 & 19
15	Photograph 20

NB: This document is intended to be printed A3 Landscape format







Photograph 1: Area 1 McLaughlins Road frontage looking east. Existing pin oaks along boundary
 Taken: 20/05/2019 4:54pm
 FL: 25



Photograph 2: McLaughlins Road (site) frontage looking east
 Taken: 20/05/2019 4:55pm
 FL: 25



Photograph 3: Area 1 Greendale Road water race looking east
 Taken: 20/05/2019 4:42pm
 FL: 25



Photograph 4: Area 1 Greendale Road water race looking north
 Taken: 20/05/2019 4:42pm
 FL: 25



Photograph 5: Area 1-2 Greendale Road frontage looking west-east
Taken: 20/05/2019 4:36pm
FL: 25



Photograph 6: Area 2 - Creyke Road boundary looking northwest

Taken: 20/05/2019 5:38pm

FL: 25



Photograph 7: Area 2 - OP zone interface

Taken: 20/05/2019 5:38pm

FL: 25



Photograph 8: Area 2 Creyke Road frontage looking northwest
 Taken: 20/05/2019 4:19pm
 FL: 25



Photograph 9: Area 2 Creyke Road OP zone interface
 Taken: 20/05/2019 4:19pm
 FL: 25



Photograph 10: Area 1 McLaughlins Road looking southwest looking to L2 Zone opposite
 Taken: 20/05/2019 4:59pm
 FL: 25



Photograph 11: Area 1 McLaughlins Road L1 interface
 Taken: 20/05/2019 4:59pm
 FL: 25



Photograph 12: Area 3 frontage to SH73 looking south
 Taken: 20/05/2019 5:51pm
 FL: 25



Photograph 13: Area 4A frontage looking southeast from SH73

Taken: 20/05/2019 5:18pm

FL: 25



Photograph 14: Cridges Road context - looking east
 Taken: 20/05/2019 5:12pm
 FL: 25



Photograph 15: Area 4B - entry from Cridges Road looking west
 Taken: 20/05/2019 5:12pm
 FL: 25



Photograph 16: Area 4B from SH77/Bangor Road looking north
 Taken: 20/05/2019 5:05pm
 FL: 25



Photograph 17: Area 5 - Homebush Road boundary looking west
 Taken: 20/05/2019 5:26pm
 FL: 25



Photograph 18: Area 5 - Homebush Road boundary looking east
 Taken: 20/05/2019 5:27pm
 FL: 25



Photgarph 19: Homebush Road boundary looking south into site
 Taken: 20/05/2019 5:26pm
 FL: 25



Photograph 20: Area 5 - looking north from Landsborough Drive

Taken: 20/05/2019 5:38pm

FL: 25