



- SITE INFO:**
- 157 Levi Road
Rolleston, Selwyn District, Canterbury
- Legal Description:
RS 7556 BLK III LEESTON SD
- All inlets, sumps, etc to be protected with appropriate filter system during construction to protect soakpits and stormwater filter systems**
- Site Area 71,831m²
Site Coverage 11.3%
- Erosion & sediment control measures to comply with "Environment Canterbury Erosion & Sediment Control Guidelines for Small Sites"**
- Provide dust control measures including**
-dampening any excavated surface covering stockpiles as required
-dampening loaded vehicles if required to minimise material loss during transit
- SITE FENCES:**
During construction site fences are to comply with NZBC F5/AS1 Construction and Demolition Hazards
- Contractor to allow to clean up roads**
- Contractor to manage chemical spills/ contamination during works and manage on-site vehicle fueling**
- Key**
- Silt Fence (on downstream side of site)
 - Stabilised entry
 - Sumps with sump protection (Bidim A29 filter fabric)
 - Soakpits
 - Extg site contours

Aerial photo of extg site showing extg buildings, planting shelter belts etc.